



REV	DESCRIPTION
.001	R2 ADDED TO REC TALLY FOR PULLUP.
.00A 9-21-88 AD	DWG# 30-0034-00A WAS FILE 40.002. PAIR COLORS, UNUSED PAIR INFO ADDED, LYNX PIN 12 ADDED.
B 4/21/89 MC	REHEARSE CMD. ADDED TO PIN BB ON CONN. B
C 1/5/90 BT	ADDED PLAY TALLY; CHANGED DWG. #: WAS 30-0034-00B
D 5/13/90 BT	MODIFY SERVO RELAY CONNECTION TO ACCOMMODATE TASC ATR-80; CORRECT PLAY TALLY PIN DESIGNATION ON MACH. END OF CABLE.
E 6/20/90 BT	CORRECT GROUND PIN ON CONN. B TO ACCOMMODATE ATR-80; ADD REV 'B' NOTES
REV F 4/22/91 MS	CORRECTED TYPO. MAIN UNIT GND ON CONN 'B' WAS 'RR'. UPDATED TITLE BLOCK.

TEN PAIR CABLE UNUSED PAIR:  
NONE

\*= LYNX MODULES WITH U20 ONLY

CABLE APPLIES TO:  
40-SERIES ATR-60 SERIES  
MS-16

(C) 1991 TIMELINE, INC. 2401 Dogwood Way Vista CA 92083		APP'D MC
SCHEMATIC CABLE ASSEMBLY TASCAM TYPE A		CHK'D
CONFIDENTIAL	DATE	4/22/91
DWG 70D039-20	REV F	PAGE 1
	OF 1	SIZE B

70D039-20-1  
 TASCAM TYPE 'A'  
 REV F